

ROUTING AND RECORD SHEET

SUBJECT: (Optional)

Wang Alliance System

DD/A Registry

83-1694

FROM: Harry E. Fitzwater
Deputy Director for Administration

EXTENSION:

NO.

DATE 30 June 1983

STAT

TO: (Officer designation, room number, and building)

DATE

RECEIVED

FORWARDED

OFFICER'S INITIALS

COMMENTS (Number each comment to show from whom to whom. Draw a line across column after each comment.)

1. Chief, Career Training Task Force

2. 626 CoC

3.

4.

5.

6.

7.

8.

9.

10.

11.

12.

13.

14.

15.

DD/A REGISTRY
FILE: 504

DDA/HEFitzwater:cn (30 Jun 83)

Distribution:

Original PRS - Addressee w/att
1 - DDA Subject w/att
1 - DDA Chrono w/o att
1 - HEF Chrono w/o attAtt: Telephone Message for DDA from DD/OL,
dtd 30 Jun 83, Same Subject

83-1694

STAT

C/CT Task Force

1700 hrs
30 June 1983

NOTE FOR: DDA

SUBJECT: Wang Alliance System

STAT

It requires that the heat be removed from the room in which the CPU of the Alliance system is installed. We were going through GSA but will do it direct to get it done immediately. [] is getting a package air handler system that will hook into the chill water system already in C of C. As of 1700 hours Thursday (30 June), he was waiting a call from [], building manager at C of C, to see if [] was successful in getting his contractor to cut the hole into the chill water system. [] is going to use petty cash for a lease purchase of the air handler system or have another flown in from Texas, whichever is quicker. I will call [] today and will give you an update later tomorrow afternoon.

STAT

STAT

STAT

STAT

STAT

[]

STAT

[]

STAT

This is the latest.

[]

STAT